

序号	报告编号	发布日期	结论	影像资料
27	GX-B1328/20-7-24053	2024年10月24日	本次共检验电器20支，20支所检项目合格。	 <p>A photograph showing an electrical inspection setup in a room. A worker wearing a red helmet is kneeling on the floor, working with equipment. A wooden chair is positioned in the center, with a yellow bucket placed next to it. The room contains electrical cabinets and various tools. A timestamp '2024/10/24' is visible in the bottom right corner of the image.</p>
28	GX-B1328/20-7-24054	2024年10月24日	本次共检便携式接地和接地短路装置19组，19组所检项目合格。	 <p>A photograph showing an electrical inspection setup in a room, similar to the one above. A worker wearing a red helmet is kneeling on the floor, working with equipment. A wooden chair is positioned in the center, with a yellow bucket placed next to it. The room contains electrical cabinets and various tools. A timestamp '2024/10/24' is visible in the bottom right corner of the image.</p>

29	GX-B1328/20-7-24055	2024年10月24日	本次共检绝缘杆2支，2支所检项目合格。	
30	GX-B1328/20-7-24056	2024. 10. 25	所检项目合格。	

31	GX-B1328/20-7-24057	2024. 10. 25	所检项目合格。	
32	GX-B1328/20-7-24058	2024. 10. 29	所检项目合格。	

33	GX-B1328/20-7-24059	2024. 10. 29	所检项目合格。	
34	GX-B1328/20-7-24060	2024. 10. 29	所检项目合格。	

35	GX-B1328/20-7-24061	2024. 10. 29	所检项目合格。	
36	GX-B1515/22-7-24017	2024. 10. 30	所检项目合格。	

37	GX-B1515/22-7-24018	2024. 10. 30	所检项目合格。	 <p>DSJ 2000000_000000 2024/10/17 16:01:03</p>
38	GX-B1381/20-7-24009	2024. 11. 1	除上述问题外，其余所检项目合格。	 <p>2024/04/28</p>