

序号	报告编号	发布日期	结论	影像资料
60	GX-B1364/22-A-25008	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
61	GX-B1364/22-A-25009	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
62	GX-B1364/22-A-25010	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
63	GX-B1364/22-A-25011	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
64	GX-B1364/22-A-25012	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
65	GX-B1364/22-A-25013	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
66	GX-B1364/22-A-25014	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
67	GX-B1364/22-A-25015	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
68	GX-B1364/22-A-25016	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
69	GX-B1364/22-A-25017	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
70	GX-B1364/22-A-25018	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
71	GX-B1369/20-A-25001	2025/1/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
72	GX-B1364/22-A-25019	2025/1/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
73	GX-B1364/22-A-25020	2025/1/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
74	GX-B1364/22-A-25021	2025/1/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
75	GX-B1364/22-A-25022	2025/1/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
76	GX-B1363/22-A-25014	2025/1/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
77	GX-B1364/22-A-25002	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
78	GX-B1364/22-A-25003	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
79	GX-B1364/22-A-25004	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
80	GX-B1364/22-A-25023	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
81	GX-B1364/22-A-25024	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
82	GX-B1364/22-A-25025	2025/1/9	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
83	GX-B1364/22-A-25026	2025/1/9	成束电线电缆 燃烧试验不合格；其余所检 项目合格。	

序号	报告编号	发布日期	结论	影像资料
84	GX-B1364/22-A-25027	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
85	GX-B1364/22-A-25028	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
86	GX-B1364/22-A-25032	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
87	GX-B1364/22-A-25001	2025/1/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
88	GX-B1367/22-A-25002	2025/1/13	阻燃不合格； 其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
89	GX-B1367/22-A-25003	2025/1/13	阻燃不合格； 其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
90	GX-B1367/22-A-25004	2025/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
91	GX-B1363/22-A-25009	2025/1/13	所检项目合格。	 A photograph showing two workers in winter clothing inspecting a large, rusted metal cabinet. The cabinet has a large, conical metal chimney pipe extending from its top. One worker is on the left, and the other is on the right, both looking into the cabinet. The cabinet has yellow warning labels on its doors. A date stamp '2025.01.07' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
92	GX-B1363/22-A-25010	2025/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
93	GX-B1363/22-A-25011	2025/1/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
94	GX-B1363/22-A-25018	2025/1/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
95	GX-B1363/22-A-25016	2025/1/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
96	GX-B1363/22-A-25021	2025/1/15	所检项目合格。	 A photograph showing two men in a workshop or industrial setting. They are standing next to a large, dark-colored metal boiler or furnace. One man, wearing a blue jacket and glasses, is looking into the open door of the boiler. The other man, wearing a black jacket, is also looking into the boiler. A green trash bin is visible in the background. The date '2025.01.' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
97	GX-B1363/22-A-25020	2025/1/15	所检项目合格。	 A photograph showing two men in work clothes inspecting a large, rusted industrial boiler or furnace. The boiler has a tall chimney pipe on top. One man is on the left, looking into the open door of the boiler, and the other is on the right, also looking inside. A yellow warning sign is visible on the front of the boiler. The date '2025 01' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
98	GX-B1367/22-A-25005	2025/1/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
99	GX-B1364/22-A-25036	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
100	GX-B1364/22-A-25037	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
101	GX-B1364/22-A-25038	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
102	GX-B1364/22-A-25047	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
103	GX-B13643/22-A-25048	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
104	GX-B13643/22-A-25049	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
105	GX-B13643/22-A-25050	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
106	GX-B13643/22-A-25051	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
107	GX-B13643/22-A-25041	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
108	GX-B13643/22-A-25042	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
109	GX-B13643/22-A-25043	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
110	GX-B13643/22-A-25044	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
111	GX-B13643/22-A-25045	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
112	GX-B13643/22-A-25046	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
113	GX-B13643/22-A-25039	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
114	GX-B13643/22-A-25040	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
115	GX-B13643/22-A-25062	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
116	GX-B13643/22-A-25063	2025/1/16	所检项目合格。	 A photograph showing two men in work attire inspecting a large, dark-colored industrial machine. The machine has a control panel with several digital displays and buttons. One man is wearing a light-colored jacket and glasses, while the other is wearing a dark jacket. The machine has a yellow warning triangle on its front. The background is a plain, light-colored wall. A date stamp '2025 01' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
117	GX-B13643/22-A-25064	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
118	GX-B13643/22-A-25065	2025/1/16	所检项目合格。	 A photograph showing two men in work clothes inspecting a large industrial control panel. The panel has a digital display showing '000' and several indicator lights. A yellow warning sign is visible on the panel. The date '2025.01' is printed in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
119	GX-B13643/22-A-25066	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
120	GX-B13643/22-A-25058	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
121	GX-B13643/22-A-25059	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
122	GX-B13643/22-A-25056	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
123	GX-B13643/22-A-25052	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
124	GX-B13643/22-A-25053	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
125	GX-B13643/22-A-25054	2025/1/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
126	GX-B13643/22-A-25055	2025/1/16	所检项目合格。	