

序号	报告编号	发布日期	结论	影像资料
170	GX-B1364/22-A-25031	2025/1/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
171	GX-B1364/22-A-25030	2025/1/17	所检项目合格。	 A photograph showing two men in a laboratory or industrial setting. The man on the left is wearing a dark blue jacket and glasses, and is looking at a large, dark-colored machine with a control panel. The man on the right is wearing a light grey jacket and glasses, and is looking towards the machine. The machine has a yellow warning triangle on its front panel. The date '2025' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
172	GX-B1364/22-A-25029	2025/1/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
173	GX-B1364/22-A-25035	2025/1/17	成束燃烧试验不合格，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
174	GX-B1364/22-A-25034	2025/1/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
175	GX-B13643/22-A-25033	2025/1/17	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
176	GX-B1538/22-A-25004	2025/1/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
177	GX-B1538/22-A-25003	2025/1/17	所检项目合格。	




序号	报告编号	发布日期	结论	影像资料
178	GX-B1538/22-A-25001	2025/1/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
179	GX-B1538/22-A-25002	2025/1/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
180	GX-B1538/22-A-25005	2025/1/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
181	GX-B1538/22-A-25006	2025/1/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
182	GX-B1538/22-A-25007	2025/1/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
183	GX-B1364/22-A-25080	2025/1/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
184	GX-B1364/22-A-25081	2025/1/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
185	GX-B1364/22-A-25082	2025/1/20	所检项目合格。	



序号	报告编号	发布日期	结论	影像资料
186	GX-B1364/22-A-25083	2025/1/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
187	GX-B1363/22-A-25028	2025/1/20	所检项目合格。	 A photograph showing two men in work clothes inspecting a large, industrial furnace or boiler. The furnace is a large, rectangular metal structure with a door open. One man is wearing a blue jacket and yellow gloves, and the other is wearing a grey jacket. They are standing in a room with a window and a large green fan. The date '2025.01.' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
188	GX-B1364/22-A-25057	2025/1/20	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
189	GX-B1363/22-A-25025	2025/1/17	全厚度拉伸强度为；1243N/mm；全厚度拉断伸长率为；40%；其余所检项目合格。	 A photograph showing two men in a laboratory or industrial setting. They are standing in front of a piece of equipment, possibly a testing machine, which has a yellow radiation warning sign on it. The man on the left is wearing a dark blue jacket, and the man on the right is wearing a dark grey puffer jacket. The equipment is dark grey with a blue panel on top. The date '2025.01' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
190	GX-B1363/22-A-25024	2025/1/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
191	GX-B1363/22-A-25023	2025/1/17	所检项目合格。	 A photograph showing two men in a factory environment. They are standing next to a large, dark-colored industrial furnace or boiler. One man, wearing a dark jacket and dark pants, is looking into the open door of the furnace. The other man, wearing a blue jacket and dark pants, is also looking into the furnace. A large green industrial fan is visible in the background. The date '2025.01.' is printed in orange in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
192	GX-B13643/22-A-25019	2025/1/17	所检项目合格。	 A photograph showing two men in winter clothing inspecting a large, rusted industrial boiler or furnace. The boiler has a tall chimney pipe on top and a door with a yellow warning sign. The setting is an indoor industrial space with a window and a fan visible in the background.

序号	报告编号	发布日期	结论	影像资料
193	GX-B1363/22-A-25022	2025/1/20	所检项目合格。	 A photograph showing two men in winter jackets and yellow gloves inspecting a large, rusted industrial furnace or boiler. One man is on the left, looking into the open door of the furnace, while the other is on the right, also looking inside. The furnace has a yellow warning triangle on its door. In the background, there is a green trash bin and a green electric fan. A timestamp '2025.01.' is visible in the bottom right corner of the photo.



序号	报告编号	发布日期	结论	影像资料
194	GX-B1367/22-A-25011	2025/1/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
195	GX-B1363/22-A-25034	2025/1/21	所检项目合格。	 A photograph showing two men in dark jackets inspecting a large, rusted industrial furnace or boiler. The man on the left is wearing glasses and the man on the right is wearing yellow gloves. The furnace has a large cylindrical chimney pipe extending upwards. The background shows a window with a red frame. A timestamp '2025.01.' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
196	GX-B1363/22-A-25035	2025/1/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
197	GX-B1365/20-A-25004	2025/01/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
198	GX-B1366/20-A-25005	2025/01/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
199	GX-B1365/20-A-25001	2025/01/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
200	GX-B1365/20-A-25002	2025/01/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
201	GX-B1366/20-A-25001	2025/01/21	所检项目全部合格。	



序号	报告编号	发布日期	结论	影像资料
202	GX-B1366/20-A-25002	2025/01/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
203	GX-B1366/20-A-25003	2025/01/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
204	GX-B1365/20-A-25005	2025/01/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
205	GX-B1366/20-A-25006	2025/01/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
206	GX-B1365/20-A-25003	2025/01/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
207	GX-B1366/20-A-25004	2025/01/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
208	GX-B1364/22-A-25088	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
209	GX-B1364/22-A-25089	2025/1/22	所检项目合格。	



序号	报告编号	发布日期	结论	影像资料
210	GX-B1363/22-A-25038	2025/1/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
211	GX-B1363/22-A-25039	2025/1/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
212	GX-B1364/22-A-25084	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
213	GX-B1364/22-A-25085	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
214	GX-B1364/22-A-25086	2025/1/22	所检项目合格。	 A photograph showing two men in a technical environment. The man on the left is wearing a dark blue jacket and glasses, looking towards the right. The man on the right is wearing a light-colored jacket and glasses, looking at a control panel. The panel features a digital screen at the top, several analog gauges, and various buttons and indicators. A date stamp '2025.01' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
215	GX-B1364/22-A-25072	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
216	GX-B1364/22-A-25073	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
217	GX-B1364/22-A-25074	2025/1/22	所检项目合格。	



序号	报告编号	发布日期	结论	影像资料
218	GX-B1364/22-A-25075	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
219	GX-B1364/22-A-25076	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
220	GX-B1364/22-A-25077	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
221	GX-B1364/22-A-25078	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
222	GX-B1364/22-A-25079	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
223	GX-B1364/22-A-25087	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
224	GX-B1470/23-A-25001	2025/1/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
225	GX-B1363/22-A-25036	2025/1/24	所检项目合格。	



序号	报告编号	发布日期	结论	影像资料
226	GX-B1367/22-A-25012	2025/1/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
227	GX-B1363/22-A-25044	2025/1/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
228	GX-B1363/22-A-25043	2025/1/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
229	GX-B1364/22-A-25090	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
230	GX-B1364/22-A-25091	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
231	GX-B1364/22-A-25092	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
232	GX-B1364/22-A-25093	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
233	GX-B1364/22-A-25095	2025/1/24	所检项目合格。	



序号	报告编号	发布日期	结论	影像资料
234	GX-B1364/22-A-25096	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
235	GX-B1364/22-A-25097	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
236	GX-B1364/22-A-25099	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
237	GX-B1364/22-A-25098	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
238	GX-B1364/22-A-25100	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
239	GX-B1364/22-A-25101	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
240	GX-B1364/22-A-25102	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
241	GX-B1365/20-A-25007	2025/1/24	所检项目全部合格。	



序号	报告编号	发布日期	结论	影像资料
242	GX-B1366/20-A-25008	2025/1/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
243	GX-B1365/20-A-25006	2025/1/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
244	GX-B1366/20-A-25007	2025/1/24	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
245	GX-B1363/22-A-25029	2025/1/23	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
246	GX-B1367/22-A-25014	2025/1/24	所检项目合格。	 A photograph showing two individuals, likely technicians, working at a workstation. They are positioned on either side of a desk, looking down at a device or document. The person on the left is wearing a dark jacket, and the person on the right is wearing a dark hoodie. The workstation has a blue cabinet and a white surface. A date stamp in the bottom right corner of the photo reads "2025.01..".

序号	报告编号	发布日期	结论	影像资料
247	GX-B1367/22-A-25015	2025/1/24	所检项目合格。	