



序号	报告编号	发布日期	结论	影像资料
248	GX-B1362/23-A-25025	2025/1/20	所检项目合格	
249	GX-B1362/23-A-25027	2025/1/20	合格	

序号	报告编号	发布日期	结论	影像资料
250	GX-B1362/23-A-25028	2025/1/20	合格	
251	GX-B1362/23-A-25029	2025/1/20	合格	

序号	报告编号	发布日期	结论	影像资料
252	GX-B1361/22-A-25027	2025/1/20	合格	
253	GX-B1361/22-A-25028	2025/1/20	合格	



序号	报告编号	发布日期	结论	影像资料
254	GX-B1361/22-A-25029	2025/1/17	所检项目合格	
255	GX-B1361/22-A-25030	2025/1/17	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
256	GX-B1361/22-A-25031	2025/1/20	合格	 A photograph showing two workers in a factory. One worker is operating a large industrial machine, and the other is handling a tray filled with small, rectangular parts. A yellow timestamp '2025/1/9' is visible in the bottom right corner of the image.
257	GX-B1361/22-A-25032	2025/1/17	所检项目合格	 A photograph showing a worker in a factory setting, operating a large industrial machine. The worker is wearing a light-colored uniform. A yellow timestamp '2025/1/10' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
258	GX-B1361/22-A-25033	2025/1/17	所检项目合格	
259	GX-B1361/22-A-25034	2025/1/20	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
260	GX-B1361/22-A-25044	2025/1/20	所检项目合格	
261	GX-B1361/22-A-25045	2025/1/21	所检项目合格	


序号	报告编号	发布日期	结论	影像资料
262	GX-B1362/23-A-25034	2025/1/23	合格	
263	GX-B1362/23-A-25035	2025/1/23	合格	

序号	报告编号	发布日期	结论	影像资料
264	GX-B1362/23-A-25036	2025/1/23	合格	
265	GX-B1362/23-A-25037	2025/1/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
266	GX-B1361/22-A-25046	2025/1/22	不合格	
267	GX-B1361/22-A-25047	2025/1/23	不合格	

序号	报告编号	发布日期	结论	影像资料
268	GX-B1361/22-A-25048	2025/1/23	不合格	
269	GX-B1361/22-A-25049	2025/1/23	不合格	

序号	报告编号	发布日期	结论	影像资料
270	GX-B1361/22-A-25050	2025/1/23	所检项目合格	
271	GX-B1361/22-A-25051	2025/1/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
272	GX-B1361/22-A-25052	2025/1/23	所检项目合格	
273	GX-B1361/22-A-25053	2025/1/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
274	GX-B1361/22-A-25054	2025/1/22	所检项目合格	 A photograph showing a worker in a light-colored uniform and gloves operating a machine in a workshop. The worker is focused on the task. A yellow timestamp '2025/1/16' is visible in the bottom right corner of the image.
275	GX-B1361/22-A-25055	2025/1/23	所检项目合格	 A photograph showing a worker in a light-colored uniform and gloves operating a machine in a workshop. The worker is focused on the task. A yellow timestamp '2025/1/16' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
276	GX-B1361/22-A-25056	2025/1/23	所检项目合格	
277	GX-B1361/22-A-25057	2025/1/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
278	GX-B1361/22-A-25058	2025/1/23	所检项目合格	
279	GX-B1361/22-A-25059	2025/1/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
280	GX-B1361/22-A-25060	2025/1/23	所检项目合格	
281	GX-B1361/22-A-25061	2025/1/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
282	GX-B1361/22-A-25062	2025/1/23	合格	
283	GX-B1361/22-A-25063	2025/1/23	不合格	

序号	报告编号	发布日期	结论	影像资料
284	GX-B1361/22-A-25064	2025/1/23	所检项目合格	
285	GX-B1361/22-A-25065	2025/1/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
286	GX-B1361/22-A-25066	2025/1/23	所检项目合格	
287	GX-B1361/22-A-25067	2025/1/23	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
288	GX-B1361/22-A-25068	2025/1/23	所检项目合格	 A photograph showing two men in grey work clothes operating a large industrial machine in a workshop. The man on the left is adjusting the machine, while the man on the right is looking at a component. A yellow timestamp '2025/1/18' is visible in the bottom right corner of the image.
289	GX-B1361/22-A-25069	2025/1/23	所检项目合格	 A photograph showing two men in grey work clothes operating a large industrial machine in a workshop. The man on the left is adjusting the machine, while the man on the right is looking at a component. A yellow timestamp '2025/1/18' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
290	GX-B1361/22-A-25070	2025/1/23	合格	
291	GX-B1361/22-A-25071	2025/1/23	合格	

序号	报告编号	发布日期	结论	影像资料
292	GX-B1361/22-A-25072	2025/1/23	合格	 A photograph showing two men in light-colored work jackets operating a large industrial machine. They are positioned behind a white tray filled with numerous small, rectangular samples. The machine has a control panel on the left. A yellow timestamp '2025/1/19' is visible in the bottom right corner of the image.
293	GX-B1361/22-A-25073	2025/1/23	合格	 A photograph showing two men in light-colored work jackets operating a large industrial machine. They are positioned behind a white tray filled with numerous small, rectangular samples. The machine has a control panel on the left. A yellow timestamp '2025/1/19' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
294	GX-B1361/22-A-25090	2025/1/23	所检项目合格	
295	GX-B1362/23-A-25041	2025/1/23	所检项目合格	