

序号	报告编号	发布日期	结论	影像资料
127	GX-B1322/21-1-25054~25061	2025. 3. 14	本次共检验电力电缆8条, 8条电力电缆所检项目合格	
128	GX-B1322/21-1-25062~25075	2025. 3. 14	本次共检验电力电缆14条, 14条电力电缆所检项目合格	

129	GX-B1322/21-1-25076~25095	2025. 3. 14	本次共检验电力电缆20条, 20条 电力电缆所检项目合格	
130	GX-B1310/21-1- 25016	2025/3/8	符合标准要求	

131	GX-B1310/21-1- 25067	2025/3/13	符合标准要求	 A photograph showing a person in a dark environment, possibly a tunnel or underground setting. The person is wearing a dark jacket and a red headlamp. They are holding a bright light source, likely a flashlight or a specialized inspection light, which illuminates the scene. The background is dark and indistinct. A red timestamp '2025.03.27' is visible in the bottom right corner of the image.
132	GX-B1304/21-1-25003	2025/3/18	综合判定：合格。	 A photograph showing a person in a blue uniform and a blue hard hat working on a piece of machinery. The person is standing and appears to be adjusting or operating the machine. The machinery is green and red. The background is an industrial setting. A yellow timestamp '2025/3/4' is visible in the bottom right corner of the image.

133	GX-B1305/21-1-25003	2025/3/18	综合判定：合格。	
134	GX-B1305/21-1-25004	2025/3/18	综合判定：合格。	

135	GX-B1305/21-1-25005	2025/3/18	综合判定：合格。	
136	GX-B1322/21-1-25127~25128	2025/3/18	所检项目合格	

137	GX-B1329/21-1-25034~25042	2025/3/18	所检项目合格	 <p>A photograph showing a worker in a blue jacket and red helmet standing next to a piece of equipment in a control room. Another worker is kneeling in the background. The date stamp in the bottom right corner of the photo is 2025.03.12.</p>
138	GX-B1329/21-1-25028~25033	2025/3/18	所检项目合格	 <p>A photograph showing a worker in a grey jacket and red helmet kneeling next to a piece of equipment in a control room. The date stamp in the bottom right corner of the photo is 2025.03.18.</p>

139	GX-B1329/21-1-25024~25027	2025/3/18	所检项目合格	 <p>A photograph showing an industrial interior, likely a power plant or factory. Several workers in safety gear are visible in the background near large machinery or equipment. The floor is polished and reflective. A watermark at the bottom right of the photo reads "Shot on OnePlus" and "2025, 02, 13".</p>
140	GX-B1309/21-1-25011	2025/3/19	所检项目合格	 <p>A photograph of an underground tunnel or passage. The walls are rough and rocky. In the foreground, there are concrete steps leading down. Various pipes and cables are visible along the wall. The lighting is dim, with some artificial lights illuminating the scene.</p>

141	GX-B1500/21-1-25042	2025/3/19	综合判定：合格。		
142	GX-B1500/21-1-25043	2025/3/19	综合判定：合格。		

143	GX-B1500/21-1-25044	2025/3/19	综合判定：合格。	
144	GX-B1500/21-1-25045	2025/3/19	综合判定：合格。	

145	GX-B1500/21-1-25046	2025/3/19	综合判定：合格。	
146	GX-B1322/21-1-25102~25108	2025/3/19	所检项目合格	

147	GX-B1322/21-1-25096~25101	2025/3/19	所检项目合格	
-----	---------------------------	-----------	--------	---