

序号	报告编号	发布日期	结论	影像资料
11	GX-B1539/22-6-25001	2025/3/13	所检项目合格	
12	GX-B1539/22-6-25002	2025/3/13	所检项目合格	

13	GX-B1534/20-6-25004	2025/3/14	所检项目合格。		
14	GX-B1534/20-6-25005	2025/3/14	所检项目合格。		
15	GX-B1534/20-6-25006	2025/3/14	所检项目合格。		

16	GX-B1495/20-6-25129~25139	2025/3/14	本次共检互感器11组，11组互感器所检项目合格。	 <p>2025 02 07</p>
17	GX-B1495/20-6-25140~25145	2025/3/14	本次共检互感器6组，6组互感器所检项目合格。	 <p>2025 02 08</p>
18	GX-B1495/20-6-25146~25157	2025/3/14	本次共检互感器12组，12组互感器所检项目合格。	 <p>2025 02 09</p>


19	GX-B1495/20-6-25158~25179	2025/3/14	<p>本次共检互感器 22组，22组互感器所 检项目合格。</p>	
20	GX-B1495/20-6-25180~25189	2025/3/14	<p>本次共检互感器 10组，10组互感器所 检项目合格。</p>	
21	GX-B1495/20-6-25190~25203	2025/3/14	<p>本次共检互感器 14组，14组互感器所 检项目合格。</p>	

22	GX-B1495/20-6-25204~25223	2025/3/14	本次共检互感器20组，20组互感器所检项目合格。	
23	GX-B1495/20-6-25224~25228	2025/3/14	本次共检互感器5组，5组互感器所检项目合格。	
24	GX-B1495/20-6-25229~25230	2025/3/14	本次共检互感器2组，2组互感器所检项目合格。	

25	GX-B1495/20-6-25231~25245	2025/3/14	本次共检互感器15组，15组互感器所检项目合格。	
26	GX-B1495/20-6-25246~25247	2025/3/14	本次共检互感器2组，2组互感器所检项目合格。	
27	GX-B1321/20-6-25023~25026	2025/3/14	本次共检电力电缆4条，4条电力电缆所检项目合格。	

28	GX-B1321/20-6-25027~25036	2025/3/14	本次共检电力电缆10条，10条电力电缆所检项目合格。	
29	GX-B1321/20-6-25037~25048	2025/3/14	本次共检电力电缆12条，12条电力电缆所检项目合格。	
30	GX-B1321/20-6-25049~25057	2025/3/14	本次共检电力电缆9条，9条电力电缆所检项目合格。	

31	GX-B1321/20-6-25058~25066	2025/3/14	本次共检电力电缆9条，9条电力电缆所检项目合格。	
32	GX-B1321/20-6-25067~25073	2025/3/14	本次共检电力电缆7条，7条电力电缆所检项目合格。	
33	GX-B1321/20-6-25074~25085	2025/3/14	本次共检电力电缆12条，12条电力电缆所检项目合格。	

34	GX-B1321/20-6-25086~25097	2025/3/14	本次共检电力电缆12条，12条电力电缆所检项目合格。	
35	GX-B1321/20-6-25098~250105	2025/3/14	本次共检电力电缆8条，8条电力电缆所检项目合格。	
36	GX-B1321/20-6-250106~250110	2025/3/14	本次共检电力电缆5条，5条电力电缆所检项目合格。	

37	GX-B1328/20-6-25013	2025/3/14	本次共检绝缘手套80只, 80只绝缘手套合格。	
38	GX-B1328/20-6-25014	2025/3/14	本次共检全橡胶绝缘胶靴80只, 80只全橡胶绝缘胶靴合格。	
39	GX-B1328/20-6-25015	2025/3/14	本次共检验电器25支, 25支验电器合格。	


40	GX-B1328/20-6-25016	2025/3/14	<p>本次共检携带式接地和接地短路装置26套，26套携带式接地和接地短路装置合格。</p>	
41	GX-B1328/20-6-25017	2025/3/14	<p>本次共检绝缘杆3支，3支绝缘杆合格。</p>	
42	GX-B1329/21-6-25035~25038	2025/3/14	<p>本次共检氧化锌避雷器4组，4组氧化锌避雷器合格。</p>	

43	GX-B1350/21-6-25001	2025/3/14	本次共检接地装置2处，2处所检项目合格。	
44	GX-B1495/20-6-25001~25008	2025/3/14	本次共检高压开关柜8台，8台高压开关柜所检项目合格。	
45	GX-B1495/20-6-25009~25010	2025/3/14	本次共检高压开关柜2台，2台高压开关柜所检项目合格。	

46	GX-B1495/20-6-25011~25014	2025/3/14	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	
47	GX-B1495/20-6-25015~25027	2025/3/14	本次共检高压开关柜13台，13台高压开关柜所检项目合格。	
48	GX-B1495/20-6-25028~25031	2025/3/14	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	

49	GX-B1495/20-6-25032~25035	2025/3/14	本次共检高压开关柜4台，4台高压开关柜所检项目合格。	
50	GX-B1495/20-6-25036~25037	2025/3/14	本次共检高压防爆开关2台，2台高压防爆开关所检项目合格。	
51	GX-B1495/20-6-25038~25041	2025/3/14	本次共检高压防爆开关4台，4台高压防爆开关所检项目合格。	

52	GX-B1495/20-6-25042~25057	2025/3/14	本次共检高压防爆开关16台，16台高压防爆开关所检项目合格。	
53	GX-B1495/20-6-25058~25064	2025/3/14	本次共检高压防爆开关7台，7台高压防爆开关所检项目合格。	
54	GX-B1495/20-6-25065~25074	2025/3/14	本次共检高压防爆开关10台，10台高压防爆开关所检项目合格。	

55	GX-B1495/20-6-25075	2025/3/14	所检项目合格。	
56	GX-B1495/20-6-25076~25077	2025/3/14	本次共检高压防爆开关2台，2台高压防爆开关所检项目合格。	
57	GX-B1312/20-6-25008~25010	2025/3/13	本次共检电力变压器3台，3台电力变压器所检项目合格。	

58	GX-B1312/20-6-25011~25014	2025/3/13	本次共检电力变压器4台，4台电力变压器所检项目合格。	
59	GX-B1312/20-6-25015~25025	2025/3/13	本次共检电力变压器11台，11台电力变压器所检项目合格。	
60	GX-B1312/20-6-25026~25027	2025/3/13	本次共检电力变压器2台，2台电力变压器所检项目合格。	

61	GX-B1328/20-6-25029	2025/3/14	本次共检绝缘手套100只，100只绝缘手套合格。	
62	GX-B1328/20-6-25030	2025/3/14	本次共检全橡胶绝缘胶靴100只，100只全橡胶绝缘胶靴合格。	
63	GX-B1328/20-6-25031	2025/3/14	本次共检验电器12支，12支验电器合格。	

64	GX-B1328/20-6-25032	2025/3/14	本次共检携带式接地和接地短路装置6套，6套携带式接地和接地短路装置合格。	
65	GX-B1328/20-6-25033	2025/3/14	本次共检绝缘杆5套，5套绝缘杆合格。	
66	GX-B1329/21-6-25031~25034	2025/3/11	本次共检氧化锌避雷器4组，4组氧化锌避雷器所检项目合格。	

67	GX-B1321/20-6-25117~25122	2025/3/17	本次共检电力电缆6条，6条电力电缆所检项目合格。	
68	GX-B1321/20-6-25111~25116	2025/3/17	本次共检电力电缆6条，6条电力电缆所检项目合格。	
69	GX-B1323/21-6-25019~25020	2025/3/17	本次共检三相交流电动机2台，2台三相交流电动机所检项目合格。	

70	GX-B1495/20-6-25261~25274	2025/3/17	本次共检互感器14组，14组互感器所检项目合格。	
71	GX-B1495/20-6-25248~25260	2025/3/17	本次共检高压开关柜13台，13台高压开关柜所检项目合格。	
72	GX-B1427/21-6-25007	2025/3/18	符合标准要求	

73	GX-B1310/21-6-25022	2025/3/18	符合标准要求	 <p>2025.02.24</p>
74	GX-B1310/21-6-25023	2025/3/18	符合标准要求	 <p>2025.02.24</p>
75	GX-B1310/21-6-25025	2025/3/18	符合标准要求	 <p>2025.02.27</p>

76	GX-B1310/21-6-25026	2025/3/18	符合标准要求	
77	GX-B1310/21-6-25018	2025/3/18	符合标准要求	
78	GX-B1310/21-6-25019	2025/3/18	符合标准要求	

79	GX-B1310/21-6-25020	2025/3/18	符合标准要求	
80	GX-B1310/21-6-25021	2025/3/18	符合标准要求	
81	GX-B1310/21-6-25024	2025/3/18	符合标准要求	

82	GX-B1328/20-6-25036	2025/3/19	本次共检绝缘手套 8只, 8只绝缘手套合格。 。	
83	GX-B1328/20-6-25037	2025/3/19	本次共检全橡胶绝缘 胶靴10只, 10只全橡 胶绝缘胶靴合格。	
84	GX-B1328/20-6-25038	2025/3/19	本次共检验电器3支, 3支验电器合格。	

85	GX-B1328/20-6-25039	2025/3/19	本次共检携带式接地和接地短路装置4套，4套携带式接地和接地短路装置合格。	
86	GX-B1309/21-6-25002	2025/3/17	所检项目合格。	
87	GX-B1500/21-6-25004	2025/3/17	综合判定：合格。	

88	GX-B1500/21-6-25005	2025/3/17	综合判定：合格。	
89	GX-B1500/21-6-25006	2025/3/17	综合判定：合格。	
90	GX-B1500/21-6-25007	2025/3/17	综合判定：合格。	

91	GX-B1500/21-6-25008	2025/3/17	综合判定：合格。		
92	GX-B1500/21-6-25009	2025/3/17	综合判定：合格。		
93	GX-B1309/21-6-25003	2025/3/17	所检项目合格。		

94	GX-B1500/21-6-25010	2025/3/17	综合判定：合格。	
95	GX-B1500/21-6-25011	2025/3/17	综合判定：合格。	
96	GX-B1500/21-6-25012	2025/3/17	综合判定：合格。	

97	GX-B1500/21-6-25013	2025/3/17	综合判定：合格。	
98	GX-B1500/21-6-25014	2025/3/17	综合判定：合格。	
99	GX-B1312/20-6-25001~25002	2025/3/13	本次共检电力变压器2台，2台电力变压器所检项目合格。	

100	GX-B1312/20-6-25003~25005	2025/3/13	本次共检电力变压器3台，3台电力变压器所检项目合格。	
101	GX-B1312/20-6-25006~25007	2025/3/13	本次共检电力变压器2台，2台电力变压器所检项目合格。	
102	GX-B1323/21-6-25001~25004	2025/3/19	所检项目合格。	

103	GX-B1323/21-6-25005~25006	2025/3/19	所检项目合格。	 <p>DSJ_1000000_000000 2025/02/09 08:52:50</p>
104	GX-B1323/21-6-25007~25010	2025/3/19	所检项目合格。	 <p>DSJ_1000000_000000 2025/02/10 12:55:30</p>
105	GX-B1323/21-6-25011~25014	2025/3/19	所检项目合格。	 <p>DSJ_1000000_000000 2025/02/14 08:50:47</p>

106	GX-B1323/21-6-25015~25016	2025/3/19	所检项目合格。	 A worker wearing a blue uniform and a red hard hat stands next to large industrial machinery. The worker is smiling at the camera. The background shows an outdoor industrial setting with various structures and equipment. A timestamp '2025 02 13' is visible in the bottom right corner of the photo.
107	GX-B1323/21-6-25017~25018	2025/3/19	所检项目合格。	 A worker wearing a dark uniform and a red hard hat stands next to large industrial machinery. The worker is smiling at the camera. The background shows an outdoor industrial setting with various structures and equipment. A yellow toolbox is on the ground. A timestamp '2025 02 21' is visible in the bottom right corner of the photo.