

序号	报告编号	发布日期	结论	影像资料
1	GX-B1499/23-Z-25001	2025-03-14	所检项目合格。	
2	GX-B1499/23-Z-25002	2025-03-14	所检项目合格。	


3	GGX-B1499/23-Z-25003	2025-03-14	所检项目合格。	
4	GX-B1350/21-Z-25001	2025-03-13	本次共检验接地装置5处，5处所检项目合格。	
5	GX-B1350/21-Z-25002	2025-03-13	本次共检验接地装置2处，2处所检项目合格。	

6	GX-B1321/20-Z-25050	2025-03-14	所检项目合格。	
7	GX-B1321/20-Z-25051~25053	2025-03-14	本次共检验电力电缆3条，3条电力电缆所检项目合格。	
8	GX-B1321/20-Z-25054~25057	2025-03-14	本次共检验电力电缆4条，4条电力电缆所检项目合格。	

9	GX-B1321/20-Z-25058~25061	2025-03-14	本次共检验电力电缆4条，4条电力电缆所检项目合格。	 A photograph showing two workers in red hard hats and dark clothing inspecting a power cable at night. They are using flashlights to illuminate the work area. The date stamp '2025/3/3' is visible in the bottom right corner of the image.
10	GX-B1312/20-Z-25001~25004	2025-03-14	本次共检电力变压器4台，4台电力变压器所检项目合格。	 A photograph showing three workers in white uniforms and red hard hats inspecting a power transformer. One worker is kneeling and looking at a yellow toolbox, while two others stand nearby. The date stamp '2025/2/19' is visible in the bottom right corner of the image.
11	GX-B1312/20-Z-25005~25007	2025-03-14	本次共检电力变压器3台，3台电力变压器所检项目合格。	 A photograph showing two workers in white uniforms and red hard hats inspecting a power transformer. One worker is kneeling and looking at a yellow toolbox, while the other stands nearby. The date stamp '2025/2/19' is visible in the bottom right corner of the image.

12	GX-B1312/20-Z-25008	2025-03-14	所检项目合格。	
13	GX-B1312/20-Z-25009~25016	2025-03-14	本次共检电力变压器8台，8台电力变压器所检项目合格。	
14	GX-B1312/20-Z-25017~25019	2025-03-14	本次共检电力变压器3台，3台电力变压器所检项目合格。	

15	GX-B1312/20-Z-25020	2025-03-14	所检项目合格。	 A worker in a white uniform and red helmet is working on a transformer. The worker is using a tool to adjust or inspect a component on top of the transformer. The transformer has several cooling fins and a label that reads '中变 2025/2/21'.
16	GX-B1312/20-Z-25021~25026	2025-03-14	本次共检电力变压器6台，6台电力变压器所检项目合格。	 A worker in a red uniform and red helmet is inspecting a blue transformer. The worker is using a tool to check a component on the transformer. The transformer is located in a tunnel or underground facility. A yellow timestamp '2025/2/22' is visible in the bottom right corner.
17	GX-B1312/20-Z-25027~25030	2025-03-14	本次共检电力变压器4台，4台电力变压器所检项目合格。	 A worker in a white uniform and red helmet is sitting on the floor, working on a transformer. The worker is using a tool to inspect a component on the transformer. The transformer is located in a control room or office. A yellow timestamp '2025/2/22' is visible in the bottom right corner.

18	GX-B1328/20-Z-25001	2025-03-14	本次共检绝缘胶垫 50块，50块绝缘胶垫合 格。	
19	GX-B1328/20-Z-25002	2025-03-14	本次共检验电器12支， 12支验电器所检项目合 格。	
20	GX-B1328/20-Z-25003	2025-03-14	本次共检便携式接地和 接地短路装置1组，1组 便携式接地和接地短路 装置合格。	

21	GX-B1495/20-Z-25001	2025-03-17	所检项目合格。	
22	GX-B1495/20-Z-25002~25007	2025-03-17	本次共检高压开关柜6台，6台高压开关柜所检项目合格。	
23	GX-B1495/20-Z-25008~25011	2025-03-17	本次共检高压开关设备4台，4台高压开关设备所检项目合格。	

24	GX-B1495/20-Z-25012~25020	2025-03-17	本次共检高压开关设备9台，9台高压开关设备所检项目合格。	
25	GX-B1495/20-Z-25021~25033	2025-03-17	本次共检高压开关设备13台，13台高压开关设备所检项目合格。	
26	GX-B1495/20-Z-25034~25042	2025-03-17	本次共检高压开关设备9台，9台高压开关设备所检项目合格。	

27	GX-B1352/21-Z-25001~25004	2025-03-17	<p>本次共检矿用防爆低压交流真空馈电开关4台,4台矿用防爆低压交流真空馈电开关所检项目合格。</p>	
28	GX-B1352/21-Z-25005~25015	2025-03-17	<p>本次共检矿用防爆低压交流真空馈电开关11台,11台矿用防爆低压交流真空馈电开关所检项目合格。</p>	
29	GX-B1352/21-Z-25016~25046	2025-03-17	<p>本次共检高压开关设备13台,13台高压开关设备所检项目合格。</p>	

30	GX-B1352/21-Z-25047~25057	2025-03-17	<p>本次共检矿用防爆低压交流真空馈电开关11台,11台矿用防爆低压交流真空馈电开关所检项目合格。</p>	
31	GX-B1359/21-Z-25001~25002	2025-03-17	<p>本次共检矿用隔爆型照明信号综合保护装置2台,2台矿用隔爆型照明信号综合保护装置所检项目合格。</p>	
32	GX-B1359/21-Z-25003	2025-03-17	<p>所检项目合格。</p>	

33	GX-B1359/21-Z-25004~25017	2025-03-17	<p>本次共检矿用隔爆型照明信号综合保护装置14台, 14台矿用隔爆型照明信号综合保护装置所检项目合格。</p>	
34	GX-B1359/21-Z-25018~25020	2025-03-17	<p>本次共检矿用隔爆型照明信号综合保护装置3台, 3台矿用隔爆型照明信号综合保护装置所检项目合格。</p>	
35	GX-B1321/20-Z-25001~25011	2025-03-14	<p>本次共检验电力电缆11条, 11条电力电缆所检项目合格。</p>	

36	GX-B1321/20-Z-25012	2025-03-14	所检项目合格。	
37	GX-B1321/20-Z-25013~25023	2025-03-14	本次共检验电力电缆11条，11条电力电缆所检项目合格。	
38	GX-B1321/20-Z-25024~25032	2025-03-14	本次共检验电力电缆9条，9条电力电缆所检项目合格。	

39	GX-B1321/20-Z-25033~25040	2025-03-14	本次共检验电力电缆8条，8条电力电缆所检项目合格。	 <p>2025/2/22</p>
40	GX-B1321/20-Z-25041~25049	2025-03-14	本次共检验电力电缆9条，9条电力电缆所检项目合格。	 <p>2025/2/22</p>
41	GX-B1312/20-Z-25031~25035	2025-03-14	本次共检电力变压器5台，5台电力变压器所检项目合格。	 <p>2025/2/27</p>

42	GX-B1312/20-Z-25036~25041	2025-03-14	本次共检电力变压器6台，6台电力变压器所检项目合格。	 A photograph showing two workers in dark clothing and red hard hats inspecting a piece of equipment in a dark, confined space. A yellow date stamp '2025/2/28' is visible in the bottom right corner.
43	GX-B1312/20-Z-25042~25052	2025-03-14	本次共检电力变压器11台，11台电力变压器所检项目合格。	 A photograph showing two workers in dark clothing and red hard hats inspecting a piece of equipment behind a metal railing. A yellow date stamp '2025/3/1' is visible in the bottom right corner.
44	GX-B1312/20-Z-25053~25057	2025-03-14	本次共检电力变压器5台，5台电力变压器所检项目合格。	 A photograph showing two workers in dark clothing and red hard hats inspecting a piece of equipment in a dark environment. A yellow date stamp '2025/3/3' is visible in the bottom right corner.

45	GX-B1495/20-Z-25043~25056	2025-03-17	本次共检高压防爆开关14台，14台高压防爆开关所检项目合格。	
46	GX-B1495/20-Z-25057~25065	2025-03-17	本次共检高压防爆开关9台，9台高压防爆开关所检项目合格。	
47	GX-B1495/20-Z-25066~25071	2025-03-17	本次共检高压防爆开关6台，6台高压防爆开关所检项目合格。	

48	GX-B1495/20-Z-25072~25084	2025-03-17	本次共检高压防爆开关13台，13台高压防爆开关所检项目合格。	
49	GX-B1321/20-Z-25050	2025-03-14	所检项目合格。	
50	GX-B1321/20-Z-25051~25053	2025-03-14	本次共检验电力电缆3条，3条电力电缆所检项目合格。	


51	GX-B1321/20-Z-25054~25057	2025-03-14	本次共检验电力电缆4条，4条电力电缆所检项目合格。	
52	GX-B1321/20-Z-25058~25061	2025-03-14	本次共检验电力电缆4条，4条电力电缆所检项目合格。	
53	GX-B1310/21-Z-25002	2025-03-19	符合标准要求。	


54	GX-B1310/21-Z-25003	2025-03-19	符合标准要求。	
55	GX-B1310/21-Z-25004	2025-03-19	符合标准要求。	
56	GX-B1428/21-Z-25004	2025-03-19	无缺陷迹痕显示。	

57	GX-B1310/21-Z-25005	2025-03-19	符合标准要求。	
58	GX-B1428/21-Z-25005	2025-03-19	无缺陷迹痕显示。	
59	GX-B1310/21-Z-25006	2025-03-19	符合标准要求。	

60	GX-B1428/21-Z-25006	2025-03-19	无缺陷迹痕显示。	
61	GX-B1310/21-Z-25007	2025-03-19	符合标准要求。	
62	GX-B1428/21-Z-25007	2025-03-19	无缺陷迹痕显示。	

63	GX-B1310/21-Z-25008	2025-03-19	符合标准要求。	
64	GX-B1310/21-Z-25009	2025-03-19	符合标准要求。	
65	GX-B1310/21-Z-25012	2025-03-19	符合标准要求。	

66	GX-B1310/21-Z-25013	2025-03-19	符合标准要求。	 A worker wearing a red safety helmet and a dark blue jacket is standing in an industrial environment. He is holding a handheld device, possibly a tablet or a specialized tool, and looking at it. The background shows some structural elements of a facility. A yellow timestamp '2025/2/28' is visible in the bottom right corner of the photo.
67	GX-B1310/21-Z-25014	2025-03-19	符合标准要求。	 A worker wearing a red safety helmet and a dark jacket with reflective stripes is in a dark industrial setting. He has a headlamp on his helmet and is holding a device. The lighting is primarily from the headlamp and some ambient light. A yellow timestamp '2025/2/27' is visible in the bottom right corner of the photo.
68	GX-B1310/21-Z-25015	2025-03-19	符合标准要求。	 A worker wearing a red safety helmet and a dark jacket is in a dark industrial setting. He is holding a device and looking at it. The background shows some structural elements and a railing. A yellow timestamp '2025/2/28' is visible in the bottom right corner of the photo.

69	GX-B1310/21-Z-25016	2025-03-19	符合标准要求。	
70	GX-B1515/22-Z-25001	2025-03-17	所检项目合格。	
71	GX-B1515/22-Z-25002	2025-03-17	所检项目合格。	

72	GX-B1539/22-Z-25001	2025年3月19日	所检项目合格。	
73	GX-B1539/22-Z-25002	2025年3月19日	所检项目合格。	
74	GX-B1539/22-Z-25003	2025年3月19日	所检项目合格。	

75	GX-B1539/22-Z-25004	2025年3月19日	所检项目合格。	
76	GX-B1539/22-Z-25005	2025年3月19日	所检项目合格。	
77	GX-B1539/22-Z-25006	2025年3月19日	所检项目合格。	