

序号	报告编号	发布日期	结论	影像资料
148	GX-B1451/20-1-25161~25165	2025. 3. 24	本次共检继电保护装置5台，5台继电保护装置所检项目合格	 <p>2025/02/13</p>
149	GX-B1309/21-1-25013	2025. 3. 26	所检项目合格	 <p>2025/03/12</p>

150	GX-B1500/21-1-25051	2025. 3. 26	综合判定：合格	
151	GX-B1500/21-1-25052	2025. 3. 26	综合判定：合格	

152	GX-B1500/21-1-25053	2025. 3. 26	综合判定：合格	 <p>2025/03/12</p>
153	GX-B1305/21-1-25006	2025. 3. 26	综合判定：合格	 <p>Shot on OnePlus 2025/3/4</p>

154	GX-B1305/21-1-25007	2025. 3. 27	综合判定：合格	
155	GX-B1305/21-1-25008	2025. 3. 27	综合判定：合格	

156	GX-B1305/21-1-25009	2025. 3. 27	综合判定：合格	
157	GX-B1309/21-1-25006	2025. 3. 27	所检项目合格	

158	GX-B1500/21-1-25022	2025. 3. 27	综合判定：合格	
159	GX-B1500/21-1-25023	2025. 3. 27	综合判定：合格	

160	GX-B1500/21-1-25024	2025. 3. 27	综合判定：合格	
161	GX-B1500/21-1-25025	2025. 3. 27	综合判定：合格	

162	GX-B1309/21-1-25007	2025. 3. 27	所检项目合格			
163	GX-B1500/21-1-25026	2025. 3. 27	综合判定：合格			

164	GX-B1500/21-1-25027	2025. 3. 27	综合判定：合格	 A worker in a blue uniform and hard hat is standing in a tunnel. To the left, there is a green exit sign with a white arrow pointing right and the text '安全出口' (Safety Exit) and '未经许可 禁止进入' (No entry without permission). The worker is looking towards the camera. A yellow timestamp '2025/03/03' is visible in the bottom left corner of the photo.
165	GX-B1500/21-1-25028	2025. 3. 27	综合判定：合格	 A worker in a blue uniform and hard hat is kneeling in a tunnel, working on some equipment. The worker is looking towards the camera. A yellow timestamp '2025/03/03' is visible in the bottom left corner of the photo.

166	GX-B1500/21-1-25029	2025. 3. 27	综合判定：合格			
167	GX-B1309/21-1-25008	2025. 3. 26	所检项目合格			

168	GX-B1500/21-1-25030	2025. 3. 26	综合判定：合格	
169	GX-B1500/21-1-25031	2025. 3. 26	综合判定：合格	

170	GX-B1500/21-1-25032	2025. 3. 26	综合判定：合格	
171	GX-B1500/21-1-25033	2025. 3. 26	综合判定：合格	

172	GX-B1309/21-1-25009	2025. 3. 27	所检项目合格	 A photograph of a worker in a blue uniform and blue hard hat, wearing safety glasses. The worker is holding a handheld electronic device and is standing in a tunnel or underground facility. The background shows concrete walls and pipes. A vertical orange timestamp '2025/03/02' is visible on the left side of the image.
173	GX-B1500/21-1-25034	2025. 3. 26	综合判定：合格	 A photograph of a worker in a blue uniform and blue hard hat, wearing safety glasses. The worker is standing on a concrete staircase in a tunnel or underground facility. The background shows concrete walls and pipes. A vertical orange timestamp '2025/03/02' is visible on the left side of the image.

174	GX-B1500/21-1-25035	2025. 3. 26	综合判定：合格	
175	GX-B1500/21-1-25036	2025. 3. 26	综合判定：合格	

176	GX-B1500/21-1-25037	2025. 3. 26	综合判定：合格	
-----	---------------------	-------------	---------	---