

序号	报告编号	发布日期	结论	影像资料
121	GX-B1540/20-F-250288-250291	2025.3.20	所检项目合格	
122	GX-B1568/22-F-25062~25066	2025.3.20	所检项目合格	
123	GX-B1568/22-F-25067-25069	2025.3.20	所检项目合格	

124	GX-B1542/21-F-25038~25045	2025.3.20	所检项目合格	 2025.3.5
125	GX-B1528/20-F-25014~25016	2025.3.20	所检项目合格	 2025.3.5
126	GX-B1543/25-F-25027~25030	2025.3.20	所检项目合格	 2025.3.5

127	GX-B1529/20-F-25021~25024	2025.3.21	所检项目合格	
128	GX-B1540/20-F-250409-250433	2025.3.25	所检项目合格	
129	GX-B1540/20-F-250434~250440	2025.3.25	所检项目合格	

130	GX-B1540/20-F-250441-250451	2025.3.25	所检项目合格	
131	GX-B1540/20-F-250452-250460	2025.3.25	所检项目合格	
132	GX-B1544/21-F-25003-25008	2025.3.24	所检项目合格	
133	GX-B1529/20-F-25055-25065	2025.3.24	所检项目合格	

134	GX-B1529/20-F-25049-25054	2025.3.24	所检项目合格	 A photograph showing two laboratory workers in grey lab coats working inside a biosafety cabinet. The worker on the left is looking at something on the counter, while the worker on the right is looking down. The date stamp '2025.3.16' is visible in the bottom right corner of the image.
135	GX-B1528/20-F-25033-25038	2025.3.24	所检项目合格	 A photograph showing two laboratory workers in grey lab coats working inside a biosafety cabinet. The worker on the left is looking at something on the counter, while the worker on the right is looking down. The date stamp '2025.3.16' is visible in the bottom right corner of the image.
136	GX-B1528/20-F-25039-25047	2025.3.24	所检项目合格	 A photograph showing two laboratory workers in grey lab coats working inside a biosafety cabinet. The worker on the left is looking at something on the counter, while the worker on the right is looking down. The date stamp '2025.3.16' is visible in the bottom right corner of the image.
137	GX-B1550/22-F-25009-25019	2025.3.25	所检项目合格	 A photograph showing two laboratory workers in grey lab coats working inside a biosafety cabinet. The worker on the left is looking at something on the counter, while the worker on the right is looking down. The date stamp '2025.3.19' is visible in the bottom right corner of the image.

138	GX-B1372/22-F- 250191~250193	2025.3.26	本次共检验矿用低浓度载体催化式甲烷传感器 3台，3台所检项目合格	
139	GX-B1593/21-F-25037~25038	2025/3/21	本次共检验烟雾传感器2台，2台所检项目合格	
140	GX-B1601/22-F-250116~250126	2025/3/24	本次共检验矿用风速传感器11台，11台所检项目合格。	

141	GX-B1545/25-F-25047-25051	2025/3/24	本次共检验测定器5台，5台所检项目合格。	
142	GX-B1545/25-F-25052-25056	2025/3/21	本次共检验测定器5台，5台所检项目合格。	

143	GX-B1606/23-F-25061-25065	2025/3/24	本次共检验测定器5台，5台所检项目合格。	
144	GX-B1606/23-F-25066-25070	2025/3/24	本次共检验测定器5台，5台所检项目合格。	

145	GX-B1605/23-F-25061-25065	2025/3/24	本次共检验测定器5台，5台所检项目合格。	
146	GX-B1605/23-F-25066-25070	2025/3/24	本次共检验测定器5台，5台所检项目合格。	

147	GX-B1410/22-F-25139-25158	2025/3/21	本次共检验一氧化碳传感器20台，20台所检项目合格。	
148	GX-B1410/22-F-25159-25167	2025/3/24	本次共检验一氧化碳传感器9台，9台所检项目合格。	

149	GX-B1373/21-F-25138-25148	2025/3/24	本次共检验温度传感器9台，9台所检项目合格。	 A photograph showing three technicians in grey uniforms with the '中检公信' logo on their backs. They are standing in a laboratory or calibration room, looking at a piece of equipment on a counter. The date '2025.3.18' is visible in the bottom right corner of the image.
150	GX-B1540/20-F-250373~250397	2025.3.20	所检项目合格	 A photograph showing two technicians in grey uniforms with the '中检公信' logo. One technician is standing and looking at a device, while another is seated at a lab bench. The date '2025.3.14' is visible in the bottom right corner of the image.

151	GX-B1540/20-F-250398~250402	2025.3.20	所检项目合格	
152	GX-B1540/20-F-250332~250356	2025.3.20	所检项目合格	

153	GX-B1410/22-F-25129~25138	2025.3.24	所检项目合格	
154	GX-B1372/22-F-250136	2025.3.24	所检项目合格	

155	GX-B1409/22-F-25014~25022	2025.3.24	所检项目合格	
156	GX-B1603/22-F-250047~250051	2025.3.24	所检项目合格	

157	GX-B1601/22-F-250127~250134	2025.3.24	所检项目合格	
158	GX-B1412/22-F-25008~25009	2025.3.24	所检项目合格	

159	GX-B1410/22-F-25168~25187	2025.3.24	所检项目合格	
160	GX-B1372/22-F-250148~250159	2025.3.24	所检项目合格	

161	GX-B1409/22-F-25023~25033	2025.3.24	所检项目合格	
162	GX-B1411/22-F-25009~25010	2025.3.24	所检项目合格	

163	GX-B1528/20-F-25027~25029	2025.3.25	所检项目合格	 A photograph showing three technicians in a laboratory or testing room. They are wearing grey uniforms with a logo on the back that reads '中检公信'. They are gathered around a piece of electronic equipment on a bench. The date '2025.3.13' is visible in the bottom right corner of the photo.
164	GX-B1542/21-F-25048~25050	2025.3.25	所检项目合格	 A photograph showing a technician in a grey uniform sitting at a desk in a laboratory. The technician is working on a computer workstation. A piece of electronic equipment is on the desk next to the computer. The date '2025.3.11' is visible in the bottom right corner of the photo.

165	GX-B1543/25-F-25036~25040	2025.3.25	所检项目合格	
166	GX-B1529/20-F-25030~25034	2025.3.25	所检项目合格	

167	GX-B1373/21-F-25128	2025.3.25	所检项目合格	
168	GX-B1601/22-F-250105~250106	2025.3.25	所检项目合格	

169	GX-B1475/22-F-25109~25125	2025.3.25	所检项目合格	
170	GX-B1540/20-F-250357~250361	2025.3.26	所检项目合格	

171	GX-B1540/20-F-250362~250366	2025.3.26	所检项目合格	
172	GX-B1540/20-F-250367~250369	2025.3.25	所检项目合格	

173	GX-B1374/22-F-250152~250170	2025.3.26	所检项目合格	
174	GX-B1543/25-F-25041~25043	2025.3.26	所检项目合格	

175	GX-B1529/20-F-25035~25037	2025.3.25	所检项目合格	
176	GX-B1528/20-F-25022~25026	2025.3.25	所检项目合格	

177	GX-B1372/22-F-250181~250182	2025.3.25	所检项目合格	
178	GX-B1540/20-F-250463~250487	2025.3.26	所检项目合格	

179	GX-B1540/20-F-250513~250537	2025.3.26	所检项目合格	
180	GX-B1540/20-F-250488~250512	2025.3.26	所检项目合格	

181	GX-B1540/20-F-250403~250408	2025.3.26	所检项目合格	
182	GX-B1529/20-F-25047~25048	2025.3.26	所检项目合格	

183	GX-B1529/20-F-25041~25046	2025.3.26	所检项目合格	
184	GX-B1542/21-F-25051~25064	2025.3.26	所检项目合格	

185	GX-B1372/22-F-250214~250233	2025.3.26	所检项目合格	
186	GX-B1372/22-F-250194~250213	2025.3.26	所检项目合格	

187	GX-B1531/25-F-250001~250050	2025.3.27	所检项目合格	
188	GX-B1531/25-F-250051~250100	2025.3.27	所检项目合格	

189	GX-B1531/25-F-250101~250150	2025.3.27	所检项目合格	
190	GX-B1531/25-F-250151~250200	2025.3.27	所检项目合格	

191	GX-B1531/25-F-250201~250250	2025.3.27	所检项目合格	
192	GX-B1531/25-F-250251~250300	2025.3.27	所检项目合格	

193	GX-B1569/22-F-25002	2025. 3. 27	<p>通过试验室数据分析研究，优选结果如下：</p> <p>1) CO为潜伏期阶段进入到缓慢氧化升温阶段的标志性气体，临界温度T0为45℃，临界浓度为0.42 ppm。</p> <p>2) CO为缓慢氧化升温阶段进入到加速氧化升温阶段的标志性气体，临界温度为70℃，CO的临界浓度增率为0.32 ppm/min。</p> <p>C2H4为加速氧化升温阶段进入到剧烈氧化升温阶段的标志性气体，临界温度为120℃，临界浓度为0.03 ppm。</p>	
194	GX-B1603/22-F-250056-250057	2025.3.28	所检项目合格	

195	GX-B1593/21-F-25042~25051	2025.3.27	所检项目合格	
196	GX-B1374/22-F-250192-250193	2025.3.27	所检项目合格	

197	GX-B1409/22-F-25034	2025.3.28	所检项目合格	 <p>2025.3.19</p>
198	GX-B1601/21-F-250141-250152	2025.3.28	所检项目合格	 <p>2025.3.19</p>

199	GX-B1593/21-F-25039~25041	2025.3.27	所检项目合格	
200	GX-B1465/22-F-25030~25038	2025.3.31	所检项目合格	

201	GX-B1466/22-F-25026~25027	2025.3.31	所检项目合格	
202	GX-B1372/22-F-250160~250167	2025.3.31	所检项目合格	

203	GX-B1372/22-F-250168~250169	2025.3.31	所检项目合格	
204	GX-B1373/21-F-25149~25150	2025.3.31	所检项目合格	

205	GX-B1601/22-F-25135	2025.3.31	所检项目合格	
206	GX-B1374/22-F-250184~250189	2025.3.31	所检项目合格	

207	GX-B1603/22-F-25052~25055	2025.3.31	所检项目合格	
208	GX-B1540/20-F-250461-250462	2025.3.31	所检项目合格	

209	GX-B1374/22-F-250194~250199	2025.3.31	所检项目合格	
210	GX-B1528/20-F-25048-25049	2025.3.31	所检项目合格	

211	GX-B1543/25-F-25059-25060	2025.3.31	所检项目合格	 <p>2025.3.10</p>
212	GX-B1604/23-F-25021-25030	2025.3.31	所检项目合格	 <p>2025.3.20</p>

213	GX-B1604/23-F-25031-25040	2025.3.31	所检项目合格	
214	GX-B1605/23-F-25073-25074	2025. 3. 31	本次共检验测定器 2台，2台所检项目合格	
215	GX-B1374/22-F-250262-250272	2025. 3. 31	本次共检验传感器11 台，11台所检项目合格	

216	GX-B1411/22-F-25011-25013	2025.3.31	所检项目合格	 <p>2025.3.21</p>
217	GX-B1412/22-F-25010-25018	2025.3.31	所检项目合格	 <p>2025.3.20</p>

218	GX-B1412/22-F-25019-25023	2025.3.31	所检项目合格	
219	GX-B1374/22-F-250171~250183	2025.3.31	所检项目合格	